

REMEDIAL SITE ASSESSMENT DECISION - EPA NEW ENGLAND

Site Name: Bridgeport Name Plate, Inc. EPA ID#: CTD011184272

Address: 585 Fan Hill Road City: Monroe State: CT

Refer to Report Dated: November 8, 1996 Report type: Site Inspection Prioritization

Report developed by: WESTON



SDMS DocID

584727

DECISION:

☒ 1. Further Remedial Site Assessment under CERCLA (Superfund) is not required because:

☒ 1a. Site does not qualify for further remedial site assessment under CERCLA
(No Further Remedial Action Planned - NFRAP)

1b. Site may qualify for further action, but is deferred to: ☐ RCRA ☐ NRC

☐ 2. Further Assessment Needed Under CERCLA:

2a. (optional) Priority: ☐ Higher ☐ Lower

2b. Activity Type: ☐ PA ☐ SI ☐ ESI ☐ HRS evaluation

☐ Other: _____

DISCUSSION/RATIONALE: Low HRS score based on SI Worksheets (11/08/96). NFRAP peer review completed 11/14/96.

Report Reviewed
and Approved by:

Daria Till Signature: *Daria Till* Date: 11/14/96

Site Decision
Made by:

Daria Till Signature: *Daria Till* Date: 11/14/96